

The Repair of Llyn Morwinion Dam

SIMON R HICKMAN (Atkins Ltd)

ANDY K HUGHES (Atkins Ltd)

L STUART DAVIES (Dwr Cymru)

SYNOPSIS. In 2000, observed settlement of the crest of Llyn Morwinion over its outlet conduit, and sediment within this conduit associated with seepage into it, led to concern that the dam was suffering from internal erosion of the core. Initially, a remedial procedure of constructing a concrete plug in the conduit under the core was proposed but, following another inspection, it was recommended that the cause of the settlement be further investigated, the dam made good and seepage minimized. This paper describes the further investigation and recommended remedial works.

INTRODUCTION

Llyn Morwinion reservoir is retained behind a 4m high embankment dam constructed in 1879, although the water is only raised approximately 2.4 m above the lowest natural ground level, the stream level at the toe of the embankment.

The report of a Section 10 inspection of the reservoir on 18 March 2004 noted “significant leakage of sediment-bearing water into the culvert in the vicinity of the puddle clay core”. This was first noted in August 2000, as was a depression in the crest within the core zone.

A recommendation was made to fill the conduit with concrete but, following a request for Dr Hughes to carry out a further inspection, it was concluded that an alternative solution might be identified that would not restrict future entry to the conduit and, thus, access for future inspection and repair to the existing outlet pipes of cast iron and uPVC materials under the direction of a Qualified Engineer.

It was recommended that further investigation be carried out and measures taken to repair the embankment where depression had occurred, and identify where leaks into the conduit are occurring and seal these under the direction of a Qualified Civil Engineer.

ENSURING RESERVOIR SAFETY

The results of this investigation resulted in the identification of the hard horizon as shown on Figure 1.




Figure 1 – Longitudinal section identifying hard horizon & conduit

This paper describes the investigation of this leakage and its proposed remediation to ensure that the embankment is made safe.

EMBANKMENT DETAILS & HISTORY OF WORKS

The earliest information of the dam appears to be a drawing prepared in 1977 by Ward Ashcroft and Parkman in 1977 entitled, “General arrangement and section through the dam”, but there are no records of the geology of the dam site or the reservoir basin or indeed any other drawings identifying features at the dam.

This drawing identifies an embankment with a 3m wide crest with central 1.8m puddle clay core contained within vertical dry-stone walls. These are supported by a “heating” at 1 in 3.25 upstream and 1 in 2 downstream slopes surfaced by dry stone pitching. The outlet capacity was increased when the original 300m diameter cast iron outlet pipe from an upstream tower was duplicated in 1983 by a 300mm uPVC pipe passing through the original approximately 1.8m D shaped conduit. The original outlet has since been altered to be a dedicated draw-down outlet.

A draw-down facility is provided by both these pipes although the upstream inlet pipework has been moved upstream within the reservoir basin, increasing the available draw-down by over 400,000 m³.

The reservoir has a capacity of some 510,000m³ and a surface area of 113,000m², and is a very important source of water for treatment and onward transmission to the Ffestiniog area.

HICKMAN, HUGHES & DAVIES

FAILURE FEATURES

The observation in 2000 of sediment in the conduit and settlement of the crest lead to the concern that Llyn Morwinion might be in danger of failure by internal erosion.

Monitoring of seepage the quantity and quality of water into the conduit was initiated, as was deposition into the conduit.

The flow into the conduit has been measured since 2001 and the Figure 2 below demonstrates that the flow rate mirrors the changes in reservoir water level with a rate of approximately 0.32 l/s at TWL. This rate has not increased although there are variable higher rates recorded, up to 0.65 l/s in January of 2004 and 2005 which might indicate that surface rainfall into the downstream shoulder influences the flows.




Figure 2 – Leakage into the Outlet Conduit from 2001

A preliminary investigation was carried out with boreholes drilled and piezometers placed in locations indicated in Figure 3.

ENSURING RESERVOIR SAFETY




Figure 3 – Plan of Llyn Morwinion - Location of boreholes and piezometers placed in 2001




Figure 4 – Schematic log of borehole BH1 in the depression on the crest

A figurative log of the borehole drilled into the depression is given in Figure 4. Worryingly, this identified voids up to a metre below crest level and wet

HICKMAN, HUGHES & DAVIES

blue puddle clay above the crown to the conduit. The piezometers again mirrored the water level in the reservoir with a rapid response to changes in water level. At the same time survey pegs were installed in the locations shown in Figure 5.




Figure 5 – Location of survey pins placed in the crest in 2001

The levels of these pins have been taken since 2001 and their rise or fall has been charted as shown in Figure 6. Apart from the pin in the depression, Pin C, which shows downward movement, the crest is shown to be not moving. Pin C however shows a continuous year on year fall of some 10mm/year that suggests a loss of material from this zone in the core, into the conduit.




Figure 6 – Crest Settlement 1994 to 2005

ENSURING RESERVOIR SAFETY

Having identified a potential failure mode of internal erosion the Inspecting Engineer made a recommendation to fill the conduit with concrete. The Undertaker was concerned that this recommendation might not be the best solution to the problem and requested advice from Atkins.

Following an inspection, it was recommended that the conduit should not be filled with concrete, that further ground investigation be carried out to identify the route of the leak into the conduit, that this leak be sealed and the embankment be repaired, leaving the conduit open so that the pipes and valves could be maintained. It was considered important to identify the source of the leak and minimise it, rather than probably diverting it elsewhere.

GROUND INVESTIGATION

The results from the earlier ground investigations highlighted the voids and “changed” materials above the outlet conduit shown in Figure 4, but further information was required.

A Ground Investigation (GI) contract was designed to provide information on

- the condition of the core above the conduit to identify whether the sediment carried into the conduit originates from the core
- the depth of the embankment to the foundation
- the material and permeability of the foundation

as well as confirming the properties of the existing core material.

A GI contract under the ICE General Conditions of Contract Measurement Version 7th edition and Specification for ground investigation by Site Investigations Steering Group, 1993 was let with Structural Soils Limited in March 2007. Draft information was provided in April 2007 and a final data report in November 2007.

The location of the proposed boreholes and exploratory pit are shown on Figure 7.

ENSURING RESERVOIR SAFETY

A log of the trial pit excavated on the downstream section of the conduit below the embankment is given in Figure 8. Whilst the internal condition of the conduit is in good condition, the information from the trial pit introduced uncertainty into the composition and condition of material above the soffit of the conduit as well as that on the sides of the conduit appears to be constructed into an excavated trench in the rock foundation. (The rock profile is shown in Figure 1).




Figure 8 – Log of Trial Pit Downstream of the Embankment

The properties of the clay core from the results of laboratory testing are given in Tables 1 to 3.

Table 1 – Typical Moisture Content and Plasticity Index

Borehole No.	MC %	LL %	PL %	PI %	<425µm %
BH 2	23	40	22	18	99
BH 5	14 to 21	44	22	22	98

Table 2 – BH2: Soil Properties

Dia.	Passing
0.02	87
0.006	63
0.002	31

Fraction	Percentage
Gravel	3
Sand	2
Silt	64
Clay	31

HICKMAN, HUGHES & DAVIES

The strength of the clay core is shown to be satisfactory with the following results from triaxial testing.

Table 3 – BH2: Triaxial Compression Tests

Effective Cohesion (kPa)	5
Angle of Shear Resistance (degs)	27.5

The foundation material is described as a grey schist with a Rock UCS = 68MPa and a Point Load Index ($I_{S(50)}$) of 4 samples ranging from 0.2 to 5.86 (MN/m^2) $S_{(50)}$

REMEDIAL WORKS

The findings of the ground investigation confirmed the loss of material from the puddle clay core and identified the foundation of the embankment to be stable.

However, the condition of the soffit to the conduit and the interface between the conduit and the excavated trench in which the conduit was constructed remain unknown. So a function of the remedial works became a procedure for providing this information and the objectives of remedial works were therefore defined to be:

- the replacement of fissured clay material in the puddle core and making good any settlement of the core
- identification of the condition of the soffit of the outlet conduit under the puddle core
- consolidation and reduction of permeability of
 - the soffit of the conduit below the core, and
 - the zone between the conduit and the excavated trench, extending into the in-situ foundation if fractured .

The TWL is 392.3m AOD with the crest level varying from 393.93 m AOD to 393.98 m AOD, i.e. a freeboard of 1.6m. Elevation of the hard horizon immediately left of conduit (looking downstream) was found to be 390.87 m AOD and right of conduit as 390.53 m AOD. The invert of the conduit is 388.8 AOD, which demonstrates that the conduit is constructed into a trench in the foundation rock. There are not records identifying how the conduit was sealed in this trench.

The depth of core to the conduit soffit was identified to be approximately 3.3m and, with the TWL at 392.3 m AOD, the hydraulic head is 1.8m.

The evidence of sediment in the conduit and settlement of the core above the conduit indicates flow into the conduit is carrying material from the core, i.e. through the conduit soffit. However, inflow is from the side of the conduit, which suggests the flow path is through the soffit into the one of

ENSURING RESERVOIR SAFETY

construction between the conduit and the sides of the trench in foundation rock.

The puddle clay core requires remediation and its removal would make available the soffit to the conduit for inspection. The soffit would be inspected, and where possible, the zone above the sides of the conduit within the trench. It will be essential to seal this zone to restrict migration of soil particle through the soffit. Where necessary, dental concrete will be placed to provide an impervious foundation to the core when replaced. A simple grouting programme was designed to consolidate openings and seal larger interstices in the conduit soffit and sides.

As with most grouting, a flexible design is necessary with the quantity of pumped grout for a particular hole and zone limited to an acceptable maximum. The proximate conduit, because it is masonry, provides a readily available observation face but it restricts the grout pressure.

However, as eroded material had been transported via the zone to be grouted, it was considered likely that the grout would flow into the route through which the sediment has passed at a low pressure. The design includes drilling boreholes from the soffit of the conduit, shown as “a” to “d” in Figure 9 with injection of cementitious grout at low pressures as a simple grouting programme.




Figure 9 – Longitudinal Section and Embankment Cross-section identifying approximate location and alignments of proposed grout boreholes “a” to “d”

HICKMAN, HUGHES & DAVIES

The sequence of grouting and pressures will be determined from water testing. This is expected to require any necessary dental work to the soffit of the conduit to be completed prior to water tests and grouting. An alternative procedure would be to drill the grout holes and backfill the core around placed steel pipes placed into these grout holes. The benefit of the latter would be to provide a head against which to grout but close inspection would be lost.

The remedial works to the core include placing a geofabric between the core and the vertical masonry wall to reduce any possibility of migration of clay particles through the wall. The geofabric has been specified to retain $>10\mu\text{m}$, the nominal size of clay flocs behind an equivalent D_{10} of $105\ \mu\text{m}$. Clay removed from the core will be inspected and, where acceptable, re-compacted in the core. Deficiencies in quantities will be made up with imported clay of similar properties.

At the time of writing this paper in spring 2008, negotiations are ongoing with prospective contractors to carry out the work that is expected to be carried out during summer of 2008.

ACKNOWLEDGMENT

The authors acknowledge the supporting data provided by Dwr Cymru and their permission to publish this paper.

REFERENCES

Structural Soils Ltd (2007). *Factual Report on Ground Investigations of Llyn Morwynion*.